Minimum:

Maximum:

CES	: <b>A</b> :	03		Nu	mbe	er of schools re	po	rted	for CE	SA 03:	63				
1/1/	hich .	host di	oscribe	s the	loca	ation of your sch	ool	huila	lina?						
**	mon	0	0.00			ge Central City (			-	ter thar	400 000	and densi	v areater tha	n 6 000 )	
		0	0.00			l-Size Central Ci			-					•	
		0	0.00			an Fringe of Lai	•	•			-		-	,000.)	
		0	0.00			an Fringe of Mic		-			·=		· ·		
		0	0.00			ge Town (Popul			• •		•		Durouu.)		
		25	39.68			all Town (Popul		•		•	·	•	gual to 2 500	) )	
		38	60.32			ral (Population le								·· <b>/</b>	
													,		
A. P	HYSI	CAL S	STRUC	TUR	E AI	ND MECHANICA	۱L	FEA1	<b>TURES</b>						
4.	Whe	en was	s the so	chool	oriai	inally constructe	d?			<del></del>					
		-1900		1		1.61%		930-	1939	2	3.23	3%	1970-1979	3	4.84%
	190	00-190	9	3		4.84%	1	940-	1949	1	1.61	%	1980-1989	6	9.68%
	19	10-191	19	1		1.61%	1	950-	1959	14	22.58	3%	1990-1999	9	14.52%
	192	20-192	29	2		3.23%	1	960-	1969	20	32.26	5%			
5.	In v	our op	inion. i	s this	sch	ool building ovei	cro	wded	17						
	Ye	-	13	20.9		or a amamig or or		Vo	49	79.03	3%				
6	If th	e oriai:	nal hui	ldina	hac	been renovated	ori	had a	dditions	whon	was the	most rocon	t MAIOD ro	novation or	addition?
U.		Reno			18	29.03%			1949	s, wrieri 1	1.61		i, MAJOR 16: 1970-1979	3	4.84%
		fore 19			0	0.00%			1959	0	0.00		1980-1989	3	4.84%
		30-193			0	0.00%			1969	7	11.29		1990-1999	30	48.39%
7	Ном	v manv	/ total s	sauan	e fee	et does the origii	al i	huildi	ina have	2					
		nimum				Maximui			_		Median:	43,719		Average:	50,151
8	If th	e huild	lina hə	s haa	n ro	novated or adde	4 ^	n to	how mo	ny toto	l aquara t	inat aviat na	2		
O.			: 11,2		,, , <del>C</del> ,	Maximui				ny iola	Median:		)W?	Avorogo	66 004
	14111	mnam	. 11,2	.52		ividaliitiul	11.	107,0	)OO		weulan.	63,500		Average:	66,224
9.	Нои	v many				ooms were in us lools reporting th									
	Mir	nimum.	<i>:</i>	1		Maximur	n:		3		Median:	2		Average:	2
10.	Doe	s the s	school	accoi	nmo	odate any of its s	tud	lents	in instru	ıctional	facilities	located OF	F-SITE?		
	Yes			0.009			32		0.00%						
11.	Нои	v many				FTE students a nools reporting C					facilities	?			

Median:

Average:

## CESA: 03 Number of schools reported for CESA 03: 63

## Definitions for questions #12 and #15:

**Excellent:** New or easily restorable to "like new" only minimal routine maintenance.

Good: Only routine maintenance or minor repair required.

Adequate: Some preventive maintenance and/or corrective repair required.

Fair: Fails to meet code and functional requirement in some cases; extensive repair.

Poor: Consistent substandard performance; major corrective repair or overhaul.

Replace: Non-operational or significantly substandard performance. Replacement

NA: Not Applicable

12. What is the overall condition of the original buildings and the permanent additions?

	Excellent	Good	Adequate	Fair	Poor	Replace	NA
Original Buildings:	11	25	16	5	2	2	1
	<b>17.74%</b>	<b>40.32%</b>	<b>25.81%</b>	<b>8.06%</b>	<b>3.23%</b>	<b>3.23%</b>	<b>1.61%</b>
Permanent Additions:	14	19	6	3	2	1	17
	<b>22.58%</b>	<b>30.65%</b>	<b>9.68%</b>	<b>4.84%</b>	<b>3.23%</b>	<b>1.61%</b>	<b>27.42%</b>

13. What would be the total cost of all repairs/renovations/modernizations required to put this school's ON-SITE buildings in good overall condition? Number of schools reporting cost for repairs/renovations/modernizations:
26

CESA Total Costs = \$16,413,700

Minimum: \$10,000 Maximum: \$4,200,000 Median: \$250,000 Average: \$631,296

14. On which of the sources listed below is this estimate based? Choose all that apply.

34 37.36% Does not apply--already in good (or better) overall condition.

6 6.59% Facilities inspection/assessment performed within the last three years by licensed professionals.

6 6.59% Repair/renovation/modernization work already being performed/contracted for.

13 14.29% Capital improvement/facilities master plan or schedule.

23 25.27% My best professional judgement.

9 9.89% Opinions of others.

15. Overall, what is the physical condition of each of the building features listed below for this school's ON-SITE buildings?

	Excellent	Good	Adequate	Fair	Poor	Replace
Roofs:	14	27	18	1	2	0
	<b>22.58%</b>	<b>43.55%</b>	<b>29.03%</b>	<b>1.61%</b>	<b>3.23%</b>	<b>0.00%</b>
Framing, floors, foundations:	16	23	17	5	1	0
	<b>25.81%</b>	<b>37.10%</b>	<b>27.42%</b>	<b>8.06%</b>	<b>1.61%</b>	<b>0.00%</b>
Exterior walls, finishes, windows, doors:	14	28	13	6	1	0
	<b>22.58%</b>	<b>45.16%</b>	<b>20.97%</b>	<b>9.68%</b>	<b>1.61%</b>	<b>0.00%</b>
Interior finishes, trims:	13	29	14	5	1	0
	<b>20.97%</b>	<b>46.77%</b>	<b>22.58%</b>	<b>8.06%</b>	<b>1.61%</b>	<b>0.00%</b>
Plumbing:	12	25	15	6	2	2
	<b>19.35%</b>	<b>40.32%</b>	<b>24.19%</b>	<b>9.68%</b>	<b>3.23%</b>	3.23%
Heating ventilation, air conditioning:	14	25	12	9	0	2
	<b>22.58%</b>	<b>40.32%</b>	<b>19.35%</b>	<b>14.52%</b>	<b>0.00%</b>	<b>3.23%</b>
Electrical power:	16	29	6	7	3	1
	<b>25.81%</b>	<b>46.77%</b>	<b>9.68%</b>	<b>11.29%</b>	<b>4.84</b> %	1.61%
Electrical lighting:	17	30	8	6	1	0
	<b>27.42%</b>	<b>48.39%</b>	<b>12.90%</b>	<b>9.68%</b>	<b>1.61%</b>	<b>0.00%</b>
Life safety requirements (e.g., emergency lighting and warning systems, exit signs):	22	26	6	4	4	0
	<b>35.48%</b>	<b>41.94%</b>	<b>9.68%</b>	6.45%	<b>6.45</b> %	<b>0.00%</b>

Very Adequate:

Adequate:

CESA: 03 Number of schools reported for CESA 03: 63

8

22

Lighting:

12.90%

35.48%

Very Satisfactory

32.26%

20

16. How adequate is your current maintenance budget for keeping your buildings in good overall condition?

17. How satisfactory or unsatisfactory is each of the following environmental factors in this school's ON-SITE buildings?

Satisfactory

61.29%

38

Somewhat Adequate:

Not adequate at all:

25

7

Unsatisfactory

6.45%

4

40.32%

11.29%

Very Unsatisfactory

0.00%

	Minimum: 10%	Maximur	n: 10	00%		Median:	95%	Avor	age: 73	420/		
	Number of schools re	porting libra	ry/res	ource/medi	a cent	er staffed by	icensed, p	rofessional libi	rarian:	54		
26.	What percent time is your libral	ry/resource/	/media	a center sta	ffed by	a licensed, p	rofessiona	al librarian?				
<b>2</b> 5.	If you have a library/resource/r Yes 54 <b>94.74</b> %	nedia cente. No	r, is it 3	staffed by a 5.26%	a licen:	sed, professio	nal libraria	an?				
25	Minimum: .12	Maximui		3		Median:	3		rage:	3		
24.	How many classrooms would t				library		_					
	Smaller: 2 <b>3.51%</b>			me size:	4	7.02%	Larger		17%			
<b>23</b> .	How does the size of your schin your building?				center	compare with	the size o	f a typical clas	sroom			
	Yes 57 <b>91.94%</b>	No	5	8.06%								
22.	Does this school have a separ	ate room fo	r a libi	rary/resourc	e/med	lia center?						
	Minimum: 1	Maximui	<b>m</b> :	60		Median:	3	Ave	rage:	10		
21.	How many instructional classrooms have air conditioning?											
	20 <b>25.64%</b> Yes, in	the library.										
	33 <b>42.31%</b> Yes, in	computer la	ıbs.									
	25 <b>32.05%</b> Yes, in	instructiona	l class	srooms.								
20.	Does this school have air cond	ditioning in i	nstruc	tional class	rooms	, computer lai	bs, and/or	the library?				
	Yes 10 <b>16.13%</b>	No	52	83.87%								
19.	Does the school building have	CENTRAL	air co	nditioning (	cools a	all interior spa	ce)?					
	Minimum: 10	Maximu	m:	60		Median:	22	Ave	rage:	24		
	Total number of instr	uctional clas	ssroor	ns reported	in use	as of the thir	rd Friday ir	r. 1 September, 1	998:	1,506		
18	How many instructional classr	ooms were	in usa	as of the ti	hird En	iday in Santar	mhor 1009	22				
	Exterior noise		37.1		35	56.45%	4	6.45%	0	0.00%		
	Physical security of buildings		17.7		40	64.52%	11	17.74%	0	4.84% 0.00%		
	Energy efficiency/conservation		17.7		33 40	53.23% 64.52%	13 7	20.97% 11.29%	5 3	8.06%		
	Acoustics for noise control Flexibility of instructional space	· -	29.0 17.7		35	56.45%	6	9.68%	3	4.84%		
	Indoor air quality		24.1		39	62.90%	7	11.29%	1	1.61%		
	Ventilation		24.1		37	59.68%	8	12.90%	2	3.23%		
	Heating	-		42%	41	66.13%	2	3.23%	0	3.23%		

**CESA:** 03 Number of schools reported for CESA 03: 63 27. Does this school have a separate room for a parent/family center? 9 Yes 14.52% No 53 85.48% 28. How does the size of your school's parent/family center compare with the size of a typical classroom in your building? Smaller<sup>\*</sup> 3 33.33% About the same size: 55.56% Larger: 11.11% 29. How many classrooms would fit in the space used for the parent/family center? Minimum: .33 Maximum: 3 Median: Average: 1 B. SCHOOL SAFETY 30. Does your school have a "Locked Door" policy (doors can only be opened from the inside)? Yes 11 17.46% No 52 82.54% 31. Does your school have a "Check-In" policy for school visitors? Yes 54 85.71% No 9 14.29% 32. Does your school have an established emergency response plan for dealing with school safety issues? Yes 52 82.54% No 11 17.46% 33. Does your school have on-site security provided by police officers or private security guards? Yes 1 1.59% No 62 98.41% 34. Does your school have parent or other community volunteers to assist in monitoring the school? Yes 1 1.59% No 62 98.41% 35. Does your school have metal detectors? Yes 1 1.59% No 62 98.41% 36. Does your school have surveillance cameras located within the school building or on school grounds? Yes 2 3.17% No 96.83% C. EDUCATIONAL APPROPRIATENESS AND SUITABILITY **ELEMENTARY SCHOOLS ONLY** Number of Elementary Schools Reported: 34 Educational Appropriateness: 38. Size of instructional classrooms are large enough to allow for alternative room arrangements to facilitate curricular objectives. Strongly agree with statement: 12 27.91% Disagree with statement: 7 16.28% Agree with statement: 23 53.49% Strongly disagree with statement: 1 2.33% 39. Pre-kindergarten and Kindergarten space accommodates developmental range and needs of young children by providing a minimum of 35 square feet per occupant. Strongly agree with statement: 30.23% Disagree with statement: 20.93% Agree with statement: 20 46.51% Strongly disagree with statement: 2.33% 1

CESA: 03 Number of schools reported for CESA 03: 63 Number of Elementary Schools reported for CESA 03: 34 40. Adequate space is available for small work group instruction (less than 15 students). Strongly agree with statement: 13 30.23% Disagree with statement: 10 23.26% Agree with statement: 19 44.19% Strongly disagree with statement: 1 2.33% 41. Adequate space is available to allow instructional classrooms to maintain a class size of less than 30 students. Strongly agree with statement: 15 34.88% Disagree with statement: 4 9.30% 24 Agree with statement: 55.81% Strongly disagree with statement: 0 0.00% 42. Adequate space is available for large work group instruction (more than 30 students). Strongly agree with statement: 9 20.93% Disagree with statement: 14 32.56% Agree with statement: 11 25.58% Strongly disagree with statement: 9 20.93% 43. Equipment and furniture (such as shelving units, tables, and chairs) are the appropriate size for the building's student population. Strongly agree with statement: 13 30.23% Disagree with statement: 1 2.33% Agree with statement: 29 67.44% Strongly disagree with statement: 0 0.00% **Building Suitability for Education:** 44. Buildings materials, color schemes, and decor provide impetus to learning. Strongly agree with statement: 12 27.91% Disagree with statement: 3 6.98% Agree with statement: 26 60.47% Strongly disagree with statement: 2 4.65% 45. Drinking fountain and restroom facilities are an appropriate height and size for the school building population and conveniently located. Strongly agree with statement: 12 27.91% Disagree with statement: 6 13.95% Agree with statement: 25 58.14% Strongly disagree with statement: 0 0.00% 46. Student services areas (e.g., counselor and medical) ensure privacy and are of sufficient size. Strongly agree with statement: 9 20.93% Disagree with statement: 6 13.95% Agree with statement: 20 46.51% Strongly disagree with statement: 8 18.60% 47. Building is accessible to students with disabilities. Strongly agree with statement: 12 27.91% Disagree with statement: 6 13.95% Agree with statement: 22 51.16% Strongly disagree with statement: 3 6.98% 48. Space is available and appropriate for extended day learning opportunities, including before and after school day care. Strongly agree with statement: 11 28.21% Disagree with statement: 7 17.95% Agree with statement: 20 51.28% Strongly disagree with statement: 1 2.56% School Site Suitability: 49. Site is large enough to meet educational needs and is accessible. Strongly agree with statement: 13 29.55% Disagree with statement: 3 6.82% Agree with statement: 26 59.09% Strongly disagree with statement: 2 4.55%

CESA: 03 Number of schools reported for CESA 03: 63 Number of Elementary Schools reported for CESA 03: 34 50. Site has a safe outdoor space where children can engage in a variety of games, sports, and motor activities. Strongly agree with statement: 13 30.23% Disagree with statement: 0.00% Agree with statement: 29 67.44% Strongly disagree with statement: 1 2.33% Student loading areas are segregated from other vehicular traffic and pedestrian walkways. Strongly agree with statement: 16.28% Disagree with statement: 12 27.91% Agree with statement: 17 39.53% Strongly disagree with statement: 7 16.28% Playground Site and Equipment Suitability: 52. Playground size is appropriate for number of students. Strongly agree with statement: 25.58% 11 Disagree with statement: 4 9.30% Agree with statement: 27 62.79% Strongly disagree with statement: 1 2.33% 53. Playgrounds are separated from streets and parking areas with fencing or other permanent material. Strongly agree with statement: 30.23% 13 Disagree with statement: 10 23.26% Agree with statement: 17 39.53% Strongly disagree with statement: 3 6.98% 54. Playgrounds are well equipped and appropriate for age levels. Strongly agree with statement: 23.26% 9.30% Disagree with statement: 4 Agree with statement: 27 62.79% Strongly disagree with statement: 2 4.65% 55. Playground equipment is accessible to students with disabilities. Strongly agree with statement: 13.95% Disagree with statement: 11 25.58% Agree with statement: 21 48.84% Strongly disagree with statement: 5 11.63% 56. Playground equipment is free of sharp edges, of sound construction, and in good condition. Strongly agree with statement: 12 27.91% Disagree with statement: 1 2.33% Agree with statement: 29 67.44% Strongly disagree with statement: 2.33% MIDDLE, JUNIOR HIGH, AND HIGH SCHOOLS ONLY **Number of Secondary Schools Reported:** 29 Educational Appropriateness: 57. Size of instructional classrooms are large enough to allow for alternative room arrangements to facilitate curricular objectives. Strongly agree with statement: 8 25.00% Disagree with statement: 2 6.25% Agree with statement: 22 68.75% Strongly disagree with statement: 0 0.00% 58. Size and design of special learning areas (science labs, art, technology education, music and special education) is compatible with instructional need. Strongly agree with statement: 12 37.50% Disagree with statement: 6 18.75% Agree with statement: 13 40.63% Strongly disagree with statement: 1 3.13% 59. Adequate space is available for small work group instruction (less than 15 students). Strongly agree with statement: 7 21.88% Disagree with statement: 4 12.50% Agree with statement: 21 65.63% Strongly disagree with statement: 0 0.00%

29

CESA: 03	Number of sc	hool	s reported fo	r CESA 03: 63 Number of Secondary Schools report	ted for	CESA 03: 29
60. Adequate space	is available to alle	ow in	structional clas	ssrooms to maintain a class size of less than 3	30 stud	lents.
Strongly agree wit	h statement:	10	31.25%	Disagree with statement:	3	9.38%
Agree wit	h statement:	19	59.38%	Strongly disagree with statement:	0	0.00%
61. Adequate space	is available for la	rge w	vork group inst	ruction (more than 30 students).		
Strongly agree wit	h statement:	7	21.88%	Disagree with statement:	8	25.00%
Agree wit	h statement:	13	40.63%	Strongly disagree with statement:	4	12.50%
Building Suitability	for Education:					
62. Buildings materia	ls, color scheme	s, and	d decor provid	e impetus to learning.		
Strongly agree wit	h statement:	9	28.13%	Disagree with statement:	1	3.13%
Agree wit	h statement:	20	62.50%	Strongly disagree with statement:	2	6.25%
63. Drinking fountain a conveniently loca	and restroom fac ted.	ilities	are an approp	oriate height and size for the school building po	opulatio	on and
Strongly agree wit	h statement:	14	43.75%	Disagree with statement:	3	9.38%
Agree wit	h statement:	15	46.88%	Strongly disagree with statement:	0	0.00%
64. Student services	areas (e.g., cour	seloi	r and medical)	ensure privacy and are of sufficient size.		
Strongly agree wit	h statement:	9	28.13%	Disagree with statement:	7	21.88%
Agree wit	h statement:	15	46.88%	Strongly disagree with statement:	1	3.13%
65. Building is access	sible to students	with o	disabilities.			
Strongly agree wit	h statement:	11	34.38%	Disagree with statement:	3	9.38%
Agree wit	h statement:	16	50.00%	Strongly disagree with statement:	2	6.25%
66. Space is available	e and appropriate	e for e	extended day l	learning opportunities, including before and aft	ter sch	ool day care.
Strongly agree wit	h statement:	6	18.75%	Disagree with statement:	12	37.50%
Agree wit	h statement:	13	40.63%	Strongly disagree with statement:	1	3.13%
School Site Suitabili	ty:					
67. Site is large enou	gh to meet educa	ationa	al needs and is	s accessible.		
Strongly agree wit	h statement:	8	25.00%	Disagree with statement:	3	9.38%
Agree wit	h statement:	19	59.38%	Strongly disagree with statement:	2	6.25%
68. Site has a safe οι	ıtdoor space whe	ere st	udents can en	gage in a variety of games, sports, and motor	activiti	es.
Strongly agree wit	h statement:	10	31.25%	Disagree with statement:	2	6.25%
Agree wit	h statement:	18	56.25%	Strongly disagree with statement:	2	6.25%
69. Student loading a	reas are segrega	ated f	from other veh	icular traffic and pedestrian walkways.		
Strongly agree wit	h statement:	10	31.25%	Disagree with statement:	12	37.50%
Agree wit	h statement:	8	25.00%	Strongly disagree with statement:	2	6.25%